


Fig. 3A







Fig. 33

Rush Transfer (on-line) 2.5 osy, S/C "straight" Fibers



Rush Transfer

3.0 osy

(on-live)

Fig 5

Rush Transfor (cn-line)

3.205y





Fig 6

4 osy High Rush SB Rush Transfer (on-line)

Fig 7

Rush Transfer (an-Time)
0.5 osy



FI 8

Rush Transfer (on-line) 08 osy, S/S "crimped" Fibers

